

AutoCheck user log out

[Logout](#)[home](#) | [buyback registration](#) | [about us](#) | [contact us](#) | [help](#)[SHOW REPORT OPTIONS +](#)

Upgrade to Unlimited

Now that you understand the value of having a vehicle history report, *upgrade to AutoCheck unlimited for 60 days for just \$10.00.*

[Upgrade Now](#)[Run More Reports](#)Review Existing VIN: **OR** Enter New VIN:[VIN Search](#)[Print Options](#) [Show Section Details](#) [Hide Section Details](#)

Selecting "Hide" will make the report considerably smaller.

[Printable Version](#)


AutoCheck Vehicle History Report

1999 Honda CR-V LX

Report Run Date: 2009-07-24 18:36:34.359 EDT

VIN:	JHLRD1846XC067027
Year :	1999
Make :	Honda
Model:	CR-V LX
Style/Body:	SUV / Utility 4D
Class:	CUV - Entry Level
Engine:	2.0L I4 MPI
Country of Assembly:	Japan
Vehicle Age:	10 year(s)
Calculated Owners:	1
Last Reported Odometer Reading:	7

This AutoCheck Score



The AutoCheck Score is a summary of your vehicle's history, letting you compare vehicles with ease.

[About this vehicle's AutoCheck Score](#)

This vehicle qualifies for Buyback Protection



Safeguard your investment with AutoCheck Buyback Protection, which reduces the risk in buying a used vehicle.

[About Buyback Protection](#)

Section summaries

The vehicle identification number you submitted has been analyzed and summary information on your car is shown below.

- [Title and ProblemCheck:](#) ✔ Your vehicle checks out!
- [OdometerCheck:](#) ✔ Your vehicle checks out!
- [Vehicle Use and EventCheck:](#) i Specific vehicle use(s) or events reported
- [Full History:](#) i Detailed information available

[Hide Details](#)

Title and ProblemCheck



Your vehicle checks out! AutoCheck's database for this 1999 Honda CR-V LX (JHLRD1846XC067027) shows no negative titles or other problems. When [reported to AutoCheck](#), these events can indicate serious past damage or other significant problems.

0 Problem(s) Reported: 15 Title/Problem areas checked:

- ✔ No abandoned title record
- ✔ No damaged title or major damage incident record
- ✔ No fire damaged title record
- ✔ No grey market title record
- ✔ No hail damage title record
- ✔ No insurance loss title record
- ✔ No junk or scrapped title record
- ✔ No manufacturer buyback/lemon title record

- ✔ No odometer problem title record
- ✔ No rebuilt/rebuildable title record
- ✔ No salvage title or salvage auction record
- ✔ No water damaged title record
- ✔ No NHTSA crash test record
- ✔ No frame damage record
- ✔ No recycling facility record

[Hide Details](#)

OdometerCheck



Your vehicle checks out! AutoCheck examined the reported odometer readings [reported to AutoCheck](#) for this 1999 Honda CR-V LX (JHLRD1846XC067027) and no indication of an odometer rollback or tampering was found. AutoCheck uses business rules to determine if reported odometer readings are significantly less than previously reported values. Not all reported odometer readings are used. Title and auction events also report odometer tampering or breakage.

0

Problem(s) Mileage Date Reported
Reported:

✔ 7 10/07/1999

[Hide Details](#)

Vehicle Use and EventCheck



Information Reported! AutoCheck shows additional information [reported to AutoCheck](#) about how this 1999 Honda CR-V LX (JHLRD1846XC067027) has been used and other events. This includes reported accidents and corrected or duplicate titles and storm area registrations.

0 Event(s) Reported: 6 Vehicle uses checked:

- ✔ No fleet, rental and/or lease use record
- ✔ No taxi use record
- ✔ No police use record
- ✔ No government use record
- ✔ No livery use record
- ✔ No driver education record

3 Event(s) Reported: 9 Vehicle events checked:

- ✔ No accident record reported through accident data sources
- ❗ [Corrected title record\(s\)](#)
- ✔ No duplicate title record
- ❗ [Emission/safety inspection record\(s\)](#)

[Loan/Lien record\(s\)](#)

- ✔ No fire damage incident record
- ✔ No repossessed record
- ✔ No theft record
- ✔ No storm area registration/title record

Full History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date: 2009-07-24 18:36:34.359 EDT

Vehicle: 1999 Honda CR-V LX (JHLRD1846XC067027)

Event Date	Event Location	Odometer Reading	Data Source	Event Detail
09/13/1999	CHICAGO, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
10/07/1999	CHICAGO, IL	7	Motor Vehicle Dept.	TITLE (Title #:T9280636024) (Lien Reported)
09/18/2000	LISLE, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
08/14/2001	LISLE, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
09/25/2002	LISLE, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
02/01/2003	DOWNERS GROVE, IL		State Agency	PASSED EMISSION INSPECTION
07/21/2003	LISLE, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
08/16/2004	LISLE, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
01/28/2005	DOWNERS GROVE, IL		Independent Emission Source	PASSED EMISSION INSPECTION
08/08/2005	LISLE, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
08/31/2006	LISLE, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
04/21/2007	DOWNERS GROVE, IL		Independent Emission Source	PASSED EMISSION INSPECTION
07/09/2007	LISLE, IL		Motor Vehicle Dept.	TITLE (Title #:X7190678427) CORRECTED TITLE

09/06/2007 LISLE, IL	Motor Vehicle Dept.	EXCLUDED/EXEMPT REGISTRATION EVENT/RENEWAL
09/09/2008 LISLE, IL	Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL

This Vehicle's Glossary

*Below are the specific definitions for events that appear in this vehicle's report.
More information is available in the full [AutoCheck glossary](#).*

Term	Section Location	Definition
Loan/Lien	Vehicle Use and EventCheck	A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.
Emission/Safety Inspection	Vehicle Use and EventCheck	An approved emission testing station has inspected the vehicle to measure the amount of pollutants the vehicle emits into the environment.
Corrected Title	Vehicle Use and EventCheck	The State DMV has issued a corrected title for the vehicle.

AutoCheck vehicle history report Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a dealer, the dealer has been provided with these Terms & Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/consumers/disclaimer.do or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg IL 60173


AutoCheck Buyback Protection Terms and Conditions

This vehicle (JHLRD1846XC067027) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 955 American Lane Schaumburg IL 60173

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

[Home](#) | [Dealers](#) | [Become an Affiliate](#) | [Buyers Marketplace](#) | [Used Car Facts](#) | [Site Map](#)
[AutoCheck Terms and Conditions](#) | [AutoCheck Buyback Terms and Conditions](#) | [Privacy](#)
[Experian](#) | [Global Autocheck Sites](#)



Powered by Experian data

© Copyright 2009, Experian All rights reserved.